

Concerns with Harbor Freight Tools "Storehouse" Branded Blade Type Fuses

General Motors has become aware of a fuse recall by Harbor Freight Tools/Storehouse for a variety of aftermarket fuses. In two cases, these fuses have not provided protection for the wiring system of the vehicles they were customer installed in. Upon testing the 15 amp version, it was found that the fuse still would not "open" when shorted directly across the battery terminals.

How to Identify These Fuses



Packed in a 120 piece set, the fuse has a translucent, hard plastic, blue body with the amperage
© 2008 General Motors Corporation. All rights reserved.